

Lloyd's Register Verification

The Management System for:

ISO 3834-2: 2005

Quality Requirements for the Fusion Welding of Metallic Material – Comprehensive Quality Requirements

In accordance with LRV procedures, it is hereby certified that:

Telatek Service Oy

Varvintie 53, FI-92100 Raahe,

Finland

Applies a quality and welding management system in line with the above standard for the following scope:

Product Type: Steel components and constructions, repair welding , weld surfacing and special

fabrications.

Product Standards: Client Specifications, Rules of Classification Societies, AWS D1.1/1, 1M:2010, SFS EN 13445-4,

SFS EN 13480-4.

Welding and

Inspection Standards:

EN ISO5817, ASME IX, EN ISO15614 -1, EN ISO15609, EN ISO9606-1, EN 287-1, Company

Standards
Parent Materials:

Material Groups 1.1, 1.2, 1.3, 2.1, 3.1, 3.2, 5.1, 7.2, 8.1, 8.2, 9.2, 10.1 as per PD CEN

ISO/TR15608.

Welding and Allied

Processes:

BS EN ISO 4063: 2010: 111, 114, 121, 131, 135, 136, 138, 141, 152.

Responsible Welding

Co-ordinator:

Juha Rintala: (IWE FI 00430) Comprehensive knowledge

Certificate Number HEQ0005642/001

Original Approval 6 April 2016

Current Certificate 26 October 2016

Expiry Date 31 December 2021



S. C. Emeny on behalf of Lloyd's Register Verification



Working together for a safer world

Comments

Validity of the Certificate

This Certificate remains valid provided:

There is no change to the Recognised Welding Coordinator.

LRV is permitted to perform the annual verification.

No modifications occur which affect the validity of the certificate. If such modifications do occur LRV is to be informed immediately by the manufacturer so that a decision on validity of the certificate can be made.

Note:

If a valid certificate is to be renewed, the renewal must be applied for at least two months before the end of the period of validity of the current certificate.